

Supplementary Figures




Figure S1 The whole printing idea of VAN/MS-PLA/n-HA composite scaffolds.




Figure S2 Observation of Masson trichrome staining on the defect of femur in different scaffold groups at 4,8,12 weeks after operation.